## FLEET / SAFETY LETTER 04073.GEN

#### RE: EPIRB ALERTS; 24-HOUR EMERGENCY INFORMATION; OTHER RELATED ISSUES

We continue to have significant and time consuming problems regarding EPIRBs and EPIRB alerts and have identified 3 major issues: outdated emergency contact information, improper EPIRB encoding, and improper handling of EPIRBs. We encourage all owners to take a positive and pro-active approach in an attempt to assist us deal with these issues.

Accordingly, to ensure that the correct data is available, that crew members know how to handle EPIRBs, and that EPIRBs are encoded correctly, please review the following:

#### OUTDATED OR INCORRECT EMERGENCY CONTACT INFORMATION

Upon initial registration of a vessel the shipowner is required to complete Form A1. Section 39 of Form A1, "24 Hour Emergency Contact for Safety Alerts" must be fully completed. A vessel will not be registered until this section has been completed. This information is used to assist us to contact the shipowner/manager in the event of an EPIRB alert or other emergency.

Obviously, if correct information is not provided, or changes in contact details after initial registration are not provided, we will be unable to contact the shipowner in an emergency. It remains the owner's responsibility to provide updated information regularly.

We enclose as Annex 1 a new 24 Hour Emergency Contact Information form. *This form must be completed for every vessel currently registered in Vanuatu, regardless of whether the vessel is laid-up or operating. The completed form must be submitted no later than December 20, 2004.* (This form is also available on our website: www.vanuatuships.com.)

### **IMPROPER CODING OF EPIRB**

We have found that a significant number of EPIRBs in the Vanuatu fleet are improperly encoded. They must be encoded by a qualified service technician using the MMSI assigned to the vessel by this office. If the EPIRB is not properly encoded, we will be unable to identify the vessel at risk, or its owners or operators, when an alert is transmitted. Vanuatu uses the "maritime user" protocol. The Maritime Mobile Service Identity (MMSI) assigned to the vessel is made up of the MID (Marine Identification Digits) of "576," and an SSI (Ship Station Identifier) which is a 6 digit number, the last 3 digits of which are always "000." No other protocol (serialized user, maritime/location, etc.) is acceptable. Encoded call signs are not acceptable.

A vessel pending Vanuatu registration is assigned a unique MMSI number and the shipowner is sent instructions to ensure proper encoding of the EPIRB. These instructions specifically state that once the EPIRB is encoded with the assigned MMSI number, this office must be provided with the hexadecimal identification. If we do not receive the "hex ID," we will have no way of knowing if the EPIRB has been properly encoded.

Another problem associated with improper EPIRB encoding is that an EPIRB is not recoded with another MMSI when the:

- EPIRB is removed and installed on a different vessel (recoding is required)
- vessel is transferred to or from another flag (recoding with the new flag's MMSI)
- vessel is scrapped (MMSI deleted and the battery is removed from the EPIRB)

More often than not, owners fail to notify us when an EPIRB is being removed from a vessel. When an EPIRB is removed from a vessel, or a vessel is deleted from the Vanuatu registry, the MMSI assigned to the EPIRB *must* be changed. Likewise, when the EPIRB is removed from the original vessel and re-installed on another Vanuatu vessel, the EPIRB *must* be re-coded with the MMSI assigned to the receiving vessel.

There have been a number of instances where an alert has been thought to have come from a vessel to which the MMSI had been assigned, only to discover that the vessel's EPIRB did not go off. On investigation, we have found out that the original EPIRB was removed from its assigned vessel and installed on another vessel with the original MMSI still encoded in the EPIRB.

Similarly, when a vessel is transferred to another flag, the EPIRB *must* be immediately reencoded with the new flag's MMSI and this office must be notified. There have been more
than a few alerts coming from vessels that were long deleted from the registry.

Confirmation that a vessel's EPIRB has been encoded with the new MMSI number is
now required for vessel deletion. A registry cancellation certificate will only be issued
upon receipt of this confirmation.

In the very recent past, we have had numerous alerts emanating from a vessel thought to be the *El Zorro Grande II* operating in Carmen, Mexico. On investigation we found the alert continued even after the EPIRB was removed from the *El Zorro Grande II* and both the EPIRB and battery were sent ashore to the ship manager's office. To date we have not been able to identify the vessel with the activated EPIRB and are baffled as to how this could have happened.

In another case occurring at the same time as the *El Zorro Grande II* incident, we received an alert from a unit with the 576 MID but encoded with a serialized user protocol. Without that EPIRB being properly registered with us, there is no way possible to identify that vessel.

Annex 2 contains a listing of alerts during 2003 and 2004. Perhaps you will recognize one or more of the vessels. We have listed the hexadecimal IDs of the unknown vessels in case you can assist to identify the errant EPIRBs.

#### **IMPROPER HANDLING**

One common cause of false EPIRB alerts resulting in possibly as many as 50 percent of all alerts, is improper handling of the EPIRB by the ship's personnel or radio surveyors. There have been many cases where EPIRBs have been activated during testing. Manufacturers' instructions must be closely followed to ensure the unit is not inadvertently activated when being tested.

EPIRBs are sometimes activated when hit by green water in heavy seas or during water wash down. Other activations have been caused by degradation of the plastic casings or neoprene gaskets but these activations are few in comparison to improper handling and incorrect testing. .

We have even had one unit activated when thieves broke into a pleasure yacht and attempted to steal the unit.

Most false EPIRB alerts can be avoided. In fact, since 1981, we have had several hundred false alerts but only 4 true alerts.

We seek your cooperation in reducing the number of false EPIRB alerts and minimizing the related problems by asking you to follow a few simple guidelines:

- Confirm the hexadecimal code with this office once the EPIRB is encoded
- Decode the EPIRB when the vessel is deleted from the Vanuatu registry or the EPIRB is moved to another vessel
- Update the emergency contact information as soon as it changes. Submit a new Form A!, Section 39 immediately. (Note: Shipowners will now be required to complete this form on an annual basis.)
- Ensure that the crew is properly trained in handling EPIRBs

If these simple guidelines are followed, the number of false EPIRB alerts can be reduced dramatically and when the EPIRB does activate, we can quickly identify and notify the owners of the alerting vessel.

Thank you

Donald J. Sheetz Executive Vice President

Encl.

Website: <u>www.vanuatuships.com</u>

# Annex 2

# 2003 and 2004 EPIRB ALERTS

EPIRB ALERT	VESSEL NAME	EPIRB ALERT	VESSEL NAME
2003 03EPIRB001 03EPIRB002 03EPIRB003 03EPIRB004 03EPIRB005 03EPIRB006 03EPIRB007 03EPIRB008 03EPIRB009 03EPIRB010 03EPIRB011 03EPIRB012 03EPIRB013	2003 HANS TIDE OSA DUNDEE MIDNIGHT STAR MAMMOTH TIDE GSF MONITOR GULF BATTLER GULF BATTLER UNIDENTIFIABLE CHUN YING NO. 212 HOJIN MIDNIGHT STAR ARMIA KRAJOWA CRYSTAL 102 (DEL)	EPIRB ALERT  2004  04EPIRB001  04EPIRB002  04EPIRB003  04EPIRB004  04EPIRB005  04EPIRB006  04EPIRB007  04EPIRB008  04EPIRB009	VESSEL NAME  2004 UNIDENTIFIABLE OIL TRACER GSF RIG 127 PALMAS SERVICE PACIFIC GAS RICHARD PHILIPPI OSTERTOR KIKORI TIDE MISS FRIEDA
03EPIRB014 03EPIRB015 03EPIRB016 03EPIRB017 03EPIRB018 03EPIRB019 03EPIRB020 03EPIRB021 03EPIRB021 03EPIRB022 03EPIRB023 03EPIRB024 03EPIRB025 03EPIRB025 03EPIRB026 03EPIRB027 03EPIRB029 03EPIRB029 03EPIRB030 03EPIRB031 03EPIRB031	RACHEL OWEN TIDE II RUSSELL TIDE GRAND SEAHORSE CONST. SERVICE TAYLOR TIDE GLOB. COMANCHE GULF FLEET 65 PACIFIC MOON OCEAN PROJECT KOOCK TIDE WIGGINS TIDE GSF RIG 124 OCEAN CONSTRUCTOR DUSHANE TIDE FONG SEONG 818 (DSC) SUPREME HARVEST OFFSHORE MONARCH IVORY ACE	04EPIRB009 04EPIRB010 04EPIRB011 04EPIRB012 04EPIRB013 04EPIRB014 04EPIRB015 04EPIRB016 04EPIRB017 04EPIRB018 04EPIRB019 04EPIRB020 04EPIRB021	GSF BALTIC NICO RASHIDYA SEEKER SOZIDANIE (REAL) WILLIAM R CROYLE CANYON HORIZON RED FOX C8122F3911E9C74 GSF ADRIATIC IV (REAL) GSF RIG 135 PRINCESS TIDE GRANDE TIDE
03EPIRB033 OCEAN PRO NICO RASHI O3EPIRB035 MERIDIAN I THORNHILL O3EPIRB037 GLOBAL CHO O3EPIRB038 SILVER RIVE O3EPIRB039 AMAZON RIVE O3EPIRB040 GSF MONITO O3EPIRB041 AMANDA (DO O3EPIRB042 GSF MONITO O3EPIRB042 GSF MONITO O3EPIRB042	OCEAN PROJECT NICO RASHIDYA MERIDIAN I	04EPIRB022 04EPIRB023 04EPIRB024 04EPIRB025 04EPIRB026 04EPIRB027 04EPIRB028 04EPIRB029 04EPIRB030 04EPIRB031 04EPIRB032	NOT EL ZORRO GRANDE II  NOT EL ZORRO GRANDE II  C80DD39534017DA  GSF JACK RYAN  PRIDE NEVADA  C80D411F0C001AD  PRIDE NEVADA  MORECAMBE DIVER  C80D00D83497C5  ATLET 7  GSF PARAMESWARA

	Bold: Unknown or deleted vessels or real alerts.

**HEXCODE** 

# VANUATU MARITIME SERVICES LIMITED MORE THAN A FLAG OF QUALITY

42 Broadway, Suite 1200-18 New York, New York 10004-1617 website: http://www.vanuatuships.com

Telephone: 212 425-9600 Direct E-mail: drescigno@vanuatuships.com Facsimile: 212 425-9652

VESSEL NAME

Date:

## 24-HOUR EMERGENCY / OPERATIONAL CONTACT INFORMATION

**OFFICIAL** 

NUMBER

MMSI

	576 000
	576 000
	576 000
	576 000
	576 000
COMPANY/ADDRESS	
Name:	
Address:	
City/State/Country/Zip:	
CONTACT(s) DETAILS	
Name:	Title:
Telephone Number(s):	Fax:
At Home Telephone:	Mobile:
Other Numbers:	Email: @
N.	
Name:	Title:
Telephone Number(s):	Fax:
At Home:	Mobile:
Other Numbers:	Email: @

PLEASE RETURN THE COMPLETED FORM TO DEE RESCIGNO VIA FAX OR EMAIL .

THANK YOU FOR YOUR COOPERATION IN THIS MATTER.

Signature/Title: \_\_\_\_\_